



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed PRB

Report Date: **07/09/2014**

Mine Name: 2 More Feet	Permit Number: S/013/0007	Mine Status: Inactive
Operator Name: Scott Higley	Inspection Date: 06/25/2013	Permit Fees: Delinquent
Inspector(s): L. Heppler	Inspection Time: 4:48 PM	Bond Amount: \$3,000
Attendee(s): Dave Herron USFS	Weather: Sunny, Dry	Bond Escalation: 07/14/2009
Inspection Purpose: Routine annual inspection		Prior Inspection: 09/20/2010

Conclusions and Recommendations

Operator needs to pay past due permit fees and update the annual reports. OGM to continue annual inspections and monitor the site when in the area. No new work has been done to this site since the last inspection. This is a small disturbance, but nonetheless a visible disturbance for the area. A bond escalation letter was sent out on June 22, 2009.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> Permit fees are delinquent, bond escalation is past due.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> Shaft can be accessed by anyone, but depth is less than 10 feet.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> No drainages at this site	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> No deleterious material stored at this site	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> There are no roads to this site, but site can be accessed by hiking less than 1000ft	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> No concurrent reclamation was noted at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i> No regrading at the site at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i> No soil stockpiles are noted at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> No new revegetation was noted	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i> This line is intentionally left blank	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: _____

CC: Scott Higley, USFS- DAHerron@FS.Fed.us

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M013-Duchesne/S0130007-2MoreFeet/inspections/INSP-06252013.pdf





Shaft covering in the distance



Hiking down to shaft



Close-up of disturbance



Looking into the shaft